# IQ Screen Calibration Instructions (Draft Version)


1. Editor screen on start up

2. Plug USB keyboard into IQ USB socket.

3. Press **Esc** key


4. The following screen is displayed.


5. Press **Windows** key

6. The following screen is displayed.


6. Tap **Start.**

8. Tap **Settings**

9. Tap **Control Panel**


10. Double tap **Stylus**


11. Tap **Calibration**

12. Tap **Recalibrate**


13. Follow on screen instructions

14. Press **Enter** on USB keyboard to save settings

15. Tap **X** on Stylus Properties window to close


16. Tap **X** to close Control Panel window

17. Press **Windows** key.

18. The following screen is displayed


19. Tap **Start**

20. Tap **Programs**

21. Tap **Colibri Tools**

22. Tap **Save Reg**

23. Turn off power supply

24. Turn on Power Supply