

REFERENCE DRAWING


PIGMENT INSIDE WOUND

TAKE OFF SPOOL

REWIND SPOOL

CARBOARD CORE

ENSURE THE NIP ROLLER
IS ENGAGED ON DRIVE
ROLLER AFTER RENEWING
THE FOIL.



ISSUE	1	DATE	10/03/2003	TITLE	107 M THREADING DIAGRAM
DRAWN	CWP	CHECKED		SCALE	NONE
					OPEN DATE EQUIPMENT LTD
					PART NO. REF 767079